


Technical Setup Overview



Manual

Setting

1. Connect USB of the Kazamidori device to PC
2. Start PC
3. Wait 1 min (since, sometimes, the usb connection is not established)
4. Start the application of the Kazamidori
5. Make sure if the Kazamidori moves depending on the access

Trouble Shooting (if the Kazamidori doesn't work or stop)

1. Stop the application by [ESC key]
2. Unplug the USB connected to PC
3. Restart the PC
4. After completing the start of the windows, Plug the USB to the VAIO
(It takes for a while to be recognized the USB. I would say about 30sec.
The bird will be watching at N.)
5. Start the Kazamidori application on the desktop

If it's not solving, try the same procedure several times.